

Tech Tip

BLUE BIRD VISION

POWERED by ROUSH PROPANE

From your friends at New York Bus Sales

Air Compressor Coolant Lines Rubbing

Complaint - There is a coolant leak at the left front of the engine compartment

Cause - Coolant lines to the air compressor appear to be leaking

Correction - Looking above where the leak is the area in question is shown on FIGURE #1 you can see that there are 2 hoses which are wrapped in spit loom and run along the frame rail as shown in FIGURE #2. There are several options which we are all aware of to address this such as putting a section of hose on the frame rail or putting a larger hose over the loom. As you can see in FIGURE #3 we have tied the hoses back with a zip-tie which is another option. Since finding this issue, we have found that Blue Bird is routing the hoses differently and that is shown in FIGURE #4.



FIGURE #1



FIGURE #2



FIGURE #3



FIGURE #4

Thanks to our man Steve at Whitney Point Central School for pointing this out!

Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace : dwallace@newyorkbussales.com

Brian Lamaitis : blamaitis@newyorkbussales.com

ROCHESTER – phone 800-463-3232 or

Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or

Ben Reiling: breiling@newyorkbussales.com

WARRANTY – 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

PLEASE ALSO NOTE OUR NEW CUSTOMER SUPPORT REPRESENTATIVES

EAST

Gary Bigness: gbigness@newyorkbussales.com

Cell 845-500-3707

CENTRAL

JJ Richmond: jrichmond@newyorkbussales.com

Cell 315-559-3999

WEST

Mike Panzica: mpanzica@newyorkbussales.com

Cell 716-908-3186