

# Tech Tip

FROM YOUR FRIENDS AT  
NEW YORK BUS SALES!



## Flip Seat Belt Cover

- Complaint –** A child’s legs/feet were injured sitting in the seat behind the flip seat
- Cause –** The cover which screws in place (Figure #1) and is designed to cover the seat belt mounting bolts and to keep the belts from falling on the floor has become bent from when it was initially installed causing some exposed sharp edges. See Figure#1 & #2
- Correction –** There are 2 fixes that can be done –  
#1 – The cover can be removed and the screws which secured it reinstalled in the seat frame – Figures #2 & #3  
#2 – The cover can be removed, straightened and “edge guard” installed along the lower edge to cover the sharp edges – Figures #4 & #5



Figure #1



Figure #2



**Figure #3**



**Figure #4**



**Figure #5**



**Figure #6**

*Thank You to Paul Owens at Brookfield Central School for pointing this out!*

*Contact Our Service Department With Any Questions*

**CHITTENANGO** – phone 800-962-5768 or  
Daryl Wallace : [dwallace@newyorkbussales.com](mailto:dwallace@newyorkbussales.com)  
Brian Lamaitis : [blamaitis@newyorkbussales.com](mailto:blamaitis@newyorkbussales.com)

**ROCHESTER** – phone 800-463-3232 or  
Gary Chichester: [gchichester@newyorkbussales.com](mailto:gchichester@newyorkbussales.com)

**ALBANY** – phone 866-867-1100 or  
Ben Reiling: [breiling@newyorkbussales.com](mailto:breiling@newyorkbussales.com)  
Steve Searles: [ssearles@newyorkbussales.com](mailto:ssearles@newyorkbussales.com)

**WARRANTY** – 800-962-5768 ext 237  
Morgan Jenkins: [mjenkins@newyorkbussales.com](mailto:mjenkins@newyorkbussales.com)



ALL of our Tech Tips can be found on the New York Bus Sales website at  
<http://www.newyorkbussales.com/pages/bulletins.cfm>  
Or at the New York Head Mechanic website at  
<http://www.nvhma.org/viewforum.php?f=2&start=0>