

Tech Tip



From your friends at New York Bus Sales

Product Effected – Blue Bird Type C&D

- Complaint -** Checking a 2011 unit during a P/M and looking as compared to last year's units we noticed that the air tank that was located behind the rear axle between the frame rails is no longer there? Has it been moved or was it forgotten?
- Cause –** The air tank was installed on units with rear air suspension and Blue Bird learned that the tank was not necessary so removed it from production.
- Correction** No Action Required -

Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or
Daryl Wallace : dwallace@newyorkbussales.com
Brian Lamaitis : blamaitis@newyorkbussales.com

ROCHESTER – phone 800-463-3232 or
Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or
Ben Reiling: breiling@newyorkbussales.com
Steve Searles: ssearles@newyorkbussales.com



ALL of our Tech Tips can be found on the New York Bus Sales website at
<http://www.newyorkbussales.com/pages/bulletins.cfm>
Or at the New York Head Mechanic website at
<http://www.nyhma.org/viewforum.php?f=2&start=0>