

Tech Tip



From your friends at New York Bus Sales

Complaint - We just changed the pump in our tank and the unit runs worse than before or not at all.

Cause - When the new pump (Figure #1 & #2) was installed the protective cover over the pickup was not removed so fuel would not properly flow.

Correction - If it is installed without removing the protective covering and run for any amount of time, the pump will need to be replaced due to a “run dry” situation.

Figure #3 shows how the pickup should look when installed



Figure #1




Figure #2



Figure #3

PARTS REQUIRED

#10:00-00-F90000226 FUEL PUMP
TFP-90004300-R FUEL PUMP FILTER
MFC-19154400-R IN-LINE FILTER



Contact Our Service Department with Any Questions

CHITTENANGO – phone 800-962-5768 or
Daryl Wallace : dwallace@newyorkbussales.com
Brian Lamaitis : blamaitis@newyorkbussales.com

ROCHESTER – phone 800-463-3232 or
Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or
Ben Reiling: breiling@newyorkbussales.com
Steve Searles: ssearles@newyorkbussales.com

WARRANTY – 800-962-5768 ext.237
Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at
<http://www.newyorkbussales.com/pages/bulletins.cfm>