



NEW YORK BUS SALES

Tech Tip 16-0207-1

2014 and Newer BBCV Headlight Aiming

Complaint: Driver says the headlights point up or down and need to be aimed.

Cause: The newly designed hood with the “molded” headlights (Figure 1) does not have any “apparent” adjustments.

Correction: Tilting the hood and looking behind the light in the cutout of the hood you see 2 screws. The upper screw pictured in Figure 2 is the adjustment for up & down and is the only adjustment. The light itself takes care of right and left aiming.




Figure 1



Figure 2

Contact our nearest Service Department for more information

Chittenango: 315-687-3969 or 1-800-962-5768

Rochester: 585-424-3320 or 1-800-463-3232

Ravena: 518-756-1111 or 1-866-867-1111

Daryl Wallace or Brian Lamaitis

Dave Schaub

Ben Reiling

Customer Service Representatives

Eastern Region Gary Bigness 845-500-3707

Central Region JJ Richmond 315-559-3999

Western Region Mike Panzica 716-908-3186