

Tech Tip



From your friends at New York Bus Sales

Product Affected-All American “D3”

- Complaint -** The sun visor cannot be adjusted to not fully block the sun.
- Cause -** Increased windshield size!
- Correction -** The current production D3 units use the original 6 X 30 visor as pictured in Figures #1 and #2 which may not cover the same area that some drivers require. We have been working with Rosco and have found a larger visor which we feel will further adjust to cover a larger area and will be much more adaptable to drivers. Please look and Figures #3 and #4 as you can see specifically in Figure #4 the space to the left which we heard most about is addressed with this new visor!




FIGURE #1




FIGURE #2




FIGURE #3




FIGURE #4

PART #81035 - \$33.85



Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace : dwallace@newyorkbussales.com

Brian Lamaitis : blamaitis@newyorkbussales.com

ROCHESTER – phone 800-463-3232 or

Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or

Ben Reiling: breiling@newyorkbussales.com

Steve Searles: ssearles@newyorkbussales.com

WARRANTY – 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at

<http://www.newyorkbussales.com/pages/bulletins.cfm>

Or at the New York Head Mechanic website at

<http://www.nyhma.org/viewforum.php?f=2&start=0>