

Tech Tip



From your friends at New York Bus Sales

Product Affected-Units with CAT Engines

- Complaint -** I've replaced the belt tensioner and the belt still appears to not be aligned properly -
- Cause -** We have seen this issue with BOTH the Blue Bird and CAT tensioners to some degree and have not been able to do anything other than "shim" the tensioner for proper alignment. We have NOT been able to narrow the root cause on a 100% basis-
- Correction -** If you find that alignment is an issue after installing a new tensioner than we suggest trying a "Gates" tensioner – Part #38508. We have found that this address the issue in these cases.



NEW YORK BUS SALES

**THANKS TO RICH DENNISH
FROM
AMERICAN BUS AND COACH
FOR POINTING THIS OUT TO
US!!!**

Contact Our Service Department With Any Questions

CHITTENANGO – phone 800-962-5768 or

Daryl Wallace : dwallace@newyorkbussales.com

Brian Lamaitis : blamaitis@newyorkbussales.com

ROCHESTER – phone 800-463-3232 or

Gary Chichester: gchichester@newyorkbussales.com

ALBANY – phone 866-867-1100 or

Ben Reiling: breiling@newyorkbussales.com

Steve Searles: ssearles@newyorkbussales.com

WARRANTY – 800-962-5768 ext 237

Morgan Jenkins: mjenkins@newyorkbussales.com

ALL of our Tech Tips can be found on the New York Bus Sales website at

<http://www.newyorkbussales.com/pages/bulletins.cfm>

Or at the New York Head Mechanic website at

<http://www.nyhma.org/viewforum.php?f=2&start=0>