



MICRO BIRD ENTRANCE DOOR

Tech Tip #17-0322REVA



Entrance Door is Inoperative

Please Note: Corrected Part Number Below

If you have a unit with a nonworking electric door and no power at the motor, but with power at the connector for the door, your first thought might be a pinched wire. An issue has been found with diode in the wire feeding power to the door. The diode is in the 16 gauge light green wire #212, which runs from the electric motor to the connector. The diode is above the entrance door (See Figure #1). There are two different diodes, depending on options, a 1 AMP or a 6 AMP. The rating will be on the diode.

1 AMP – Part #IN4007

6 AMP – New Part #DI0012 (OLD #MR756)

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

CONTACT OUR SERVICE OR PARTS DEPARTMENT WITH ANY QUESTIONS

SERVICE

Chittenango: 800-962-5768
Daryl Wallace or Brian Lamaitis

Rochester: 800-463-3232 Dave Schaub

Albany: 866-867-1100 Ben Reiling

Warranty: 800-962-5768
Morgan Jenkins
Customer Service Representatives

Eastern Region:
Gary Bigness
845-500-3707

Central Region:
JJ Richmond
315-559-3999

Western Region:
Mike Panzica
716-908-3186

PARTS

Director of Parts
Jim Hogan
jhogan@newyorkbussales.com
607-227-5794

Chittenango: 800-962-5768
Gari McQuade
gmcquade@newyorkbussales.com
Bill Cox
bcox@newyorkbussales.com
John Lewin
jlewin@newyorkbussales.com
Dave Grant
dgrant@newyorkbussales.com

Albany: 866-867-1100
Sean Conway
sconway@newyorkbussales.com
Pat Murphy
pmurphy@newyorkbussales.com

Rochester: 800-463-3232
Dave Cook
dcook@newyorkbussales.com
Steve Hibbard
shibbard@newyorkbussales.com

ALL of our Service Updates can be found on the [New York Bus Sales website](#)
Or at the [New York Head Mechanic website](#)

